



270039000



### Minnesota Pollution Control Agency

520 Lafayette Road North  
St. Paul, MN 55155-4194

# Compliance Inspection Form

## Existing Subsurface Sewage Treatment Systems (SSTS)

Doc Type: Compliance and Enforcement

RECEIVED

For local tracking purposes:

NOV - 2 2020

ZONING

**Inspection results** based on Minnesota Pollution Control Agency (MPCA) requirements and attached forms – additional local requirements may also apply.

Submit completed form to Local Unit of Government (LUG) and system owner within 15 days

### System Status

System status on date (mm/dd/yyyy): 10/28/2020

**Compliant – Certificate of Compliance**  
*(Valid for 3 years from report date, unless shorter time frame outlined in Local Ordinance.)*

**Noncompliant – Notice of Noncompliance**  
*(See Upgrade Requirements on page 3.)*

#### Reason(s) for noncompliance (check all applicable)

- Impact on Public Health (Compliance Component #1) – Imminent threat to public health and safety
- Other Compliance Conditions (Compliance Component #3) – Imminent threat to public health and safety
- Tank Integrity (Compliance Component #2) – Failing to protect groundwater
- Other Compliance Conditions (Compliance Component #3) – Failing to protect groundwater
- Soil Separation (Compliance Component #4) – Failing to protect groundwater
- Operating permit/monitoring plan requirements (Compliance Component #5) – Noncompliant

### Property Information

Parcel ID# or Sec/Twp/Range: 270039000

Property address: 37105 Brietbach Rd Reason for inspection: real estate sale

Property owner: David Dehaut Owner's phone: \_\_\_\_\_

or

Owner's representative: \_\_\_\_\_ Representative phone: \_\_\_\_\_

Local regulatory authority: Becker County Regulatory authority phone: \_\_\_\_\_

Brief system description: 1000gal septic tank / 400ft sq drain field

Comments or recommendations:

### Certification

*I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.*

Inspector name: Don Umthun Certification number: 4549

Business name: \_\_\_\_\_ License number: 1867

Inspector signature:  Phone number: 218-252-6411

### Necessary or Locally Required Attachments

- Soil boring logs
- System/As-built drawing
- Forms per local ordinance
- Other information (list): \_\_\_\_\_

**1. Impact on Public Health – Compliance component #1 of 5**

**Compliance criteria:**

|   |   |
|---|---|
| System discharges sewage to the ground surface.             | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| System discharges sewage to drain tile or surface waters.   | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| System causes sewage backup into dwelling or establishment. | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |

**Any "yes" answer above indicates the system is an imminent threat to public health and safety.**

Comments/Explanation:

**Verification method(s):**

- Searched for surface outlet
- Searched for seeping in yard/backup in home
- Excessive ponding in soil system/D-boxes
- Homeowner testimony (See Comments/Explanation)
- "Black soil" above soil dispersal system
- System requires "emergency" pumping
- Performed dye test
- Unable to verify (See Comments/Explanation)
- Other methods not listed (See Comments/Explanation)

**2. Tank Integrity – Compliance component #2 of 5**

**Compliance criteria:**

|  |   |
|--|---|
| System consists of a seepage pit, cesspool, drywell, or leaching pit.<br><i>Seepage pits meeting 7080.2550 may be compliant if allowed in local ordinance.</i> | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |
| Sewage tank(s) leak below their designed operating depth.<br>If yes, which sewage tank(s) leaks:   | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No |

**Any "yes" answer above indicates the system is failing to protect groundwater.**

Comments/Explanation:

**Verification method(s):**

- Probed tank(s) bottom
- Examined construction records
- Examined Tank Integrity Form (Attach)
- Observed liquid level below operating depth
- Examined empty (pumped) tanks(s)
- Probed outside tank(s) for "black soil"
- Unable to verify (See Comments/Explanation)
- Other methods not listed (See Comments/Explanation)

**3. Other Compliance Conditions – Compliance component #3 of 5**

- a. Maintenance hole covers are damaged, cracked, unsecured, or appear to be structurally unsound.  Yes\*  No  Unknown
- b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety.  Yes\*  No  Unknown  
**\*System is an imminent threat to public health and safety.**

Explain:

- c. System is non-protective of ground water for other conditions as determined by inspector.  Yes\*  No  
**\*System is failing to protect groundwater.**

Explain:

**4. Soil Separation – Compliance component #4 of 5**

Date of installation: 10/28/1985  Unknown  
(mm/dd/yyyy)

Shoreland/Wellhead protection/Food beverage lodging?  Yes  No

**Compliance criteria:**

For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:  Yes  No  
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.

Non-performance systems built April 1, 1996, or later or for non-performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:  Yes  No  
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.\*

"Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules (7080.2350 or 7080.2400 (Advanced Inspector License required)  Yes  No  
Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.

**Verification method(s):**

Soil observation does not expire. Previous soil observations by two independent parties are sufficient, unless site conditions have been altered or local requirements differ.

- Conducted soil observation(s) (Attach boring logs)
- Two previous verifications (Attach boring logs)
- Not applicable (Holding tank(s), no drainfield)
- Unable to verify (See Comments/Explanation)
- Other (See Comments/Explanation)

**Comments/Explanation:**

**Indicate depths or elevations**

|  |    |
|--|----|
| A. Bottom of distribution media        | 28 |
|  | 22 |
| B. Periodically saturated soil/bedrock |    |
| C. System separation                   | 0  |
| D. Required compliance separation*     | 36 |

\*May be reduced up to 15 percent if allowed by Local Ordinance.

**Any "no" answer above indicates the system is failing to protect groundwater.**

**5. Operating Permit and Nitrogen BMP\* – Compliance component #5 of 5  Not applicable**

Is the system operated under an Operating Permit?  Yes  No If "yes", A below is required

Is the system required to employ a Nitrogen BMP?  Yes  No If "yes", B below is required

BMP = Best Management Practice(s) specified in the system design

**If the answer to both questions is "no", this section does not need to be completed.**

**Compliance criteria**

- a. Operating Permit number: \_\_\_\_\_  Yes  No  
Have the Operating Permit requirements been met?
- b. Is the required nitrogen BMP in place and properly functioning?  Yes  No

**Any "no" answer indicates Noncompliance.**

**Upgrade Requirements** (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, repaired, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.


SITE PLAN MUST BE DRAWN TO SCALE OR DIMENSION WITH NORTH ARROW.

Plan must include:

- \* Lot Dimensions
- \* Wells Within 100 feet of System
- \* Existing & Proposed Buildings
- \* Tank Access Route
- \* Slope & Direction
- \* Soil Borings
- \* Alternate Drainfield Site
- \* All ISTS Components
- \* Disturbed/Compacted Areas
- \* Lot Easements
- \* Horizontal Setbacks

Soil  
Boring  
#4

|      |               |   |
|------|---------------|---|
| 0-6  | Top<br>sand   | 10' R 3/1                                 |
| 6-22 | Sandy<br>loam | 10' R 5/4                                 |
| 22+  | sandy<br>clay | 10' R 5/4                                 |
|      | loam          | 7.5' R 5/6<br>Radar<br>clay 7/2<br>mottle |



Brinetbach R6


SEPTIC TANK

LIFT STATION

DRAINFIELD

- Distance from nearest well
- Distance from lake or stream
- Distance from occupied building
- Distance from property line
- Distance from bottom to water table

|    |
|----|
| 54 |
| —  |
| 53 |
| —  |
| —  |
| —  |



|    |
|----|
| 69 |
| —  |
| 64 |
| —  |
| —  |
| —  |

BECKER COUNTY

Department \_\_\_\_\_

Becker County Courthouse

Detroit Lakes, MN 56501

Subject \_\_\_\_\_

Name \_\_\_\_\_

Address \_\_\_\_\_


Town \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_ Date \_\_\_\_\_

Location or Legal Description \_\_\_\_\_

Remarks:

Signature \_\_\_\_\_

*M*



*B*

se/85

**CERTIFICATE OF COMPLIANCE  
SEWAGE SYSTEM**

This certificate has been issued this 1 day of NOVEMBER 19 85.

to certify compliance with regulations of Zoning Ordinance, Becker County, Minnesota.

The premises covered by this certificate are legally described as: S/4SW/4 AND GOV LOT 4

Lake No. NE Sec. 13 Twp. 142 Range 36 Twp. Name SAVANNAH

New sewer system has 1000 gal. septic tank, 50 ft. from nearest well; 300 ft. from lake, 60 ft. from occupied building, over 20 ft. from property line, drain field is 450 sq.ft. (15x30), 70 ft. from nearest well, 125 ft. from lake, 75 ft. from occupied building over 20 ft. from property line, and 10-12ft. from bottom to water table, twenty (20) yards of rock.

Owner: Name ANDREW F. AMERSLAV


Address P.O. BOX 121  
PARK RAPIDS, MN.  
56470

Zip No. \_\_\_\_\_

Permit No. SP 12-14, 266-8

Signed by: [Signature]

Zoning Administrator  
Becker County, Minnesota



DESIGN PAD

BECKER COUNTY

Department \_\_\_\_\_

Becker County Courthouse

Detroit Lakes, MN 56501

Subject \_\_\_\_\_

Name \_\_\_\_\_ *St/gst*

Address \_\_\_\_\_


Town \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_ Date \_\_\_\_\_

Location or Legal Description *SW 1/4 NE 1/4 Sec 14 T 142N R 36W*

Remarks:

*N*

Signature \_\_\_\_\_







# COUNTY OF BECKER

## Planning and Zoning

915 Lake Ave, Detroit Lakes, MN 56501  
Phone: 218-846-7314 ~ Fax: 218-846-7266

---

November 9, 2020

David J Dehaut  
37105 Brietbach Rd  
Park Rapids, MN 56470

**COPY**

Re Property: 27.0039.000

Dear Mr. Dehaut,

A compliance inspection form was submitted into our office 11/02/20 stating the existing septic system servicing the property is noncompliant per inspection conducted 10/28/20.

The existing septic system is to be upgraded, repaired, or replaced per State and County regulations. You have 10 months from the date of non-compliance to update the system.

Enclosed is a list of ISTS contractors. An application for an upgraded system must be submitted into the office, with the installation completed within 10 months.

Any questions, please contact our office at 218-846-7314. Thank you.

Nicole Hultin

*Nicole Hultin*

Office Support Specialist

# Complaints

Date of Complaint

09/30/16

Assigned To:

Julene  
*Dylan*

Status

Under Investigation

Last Name

Dehaut

First Name

Gloria

Mailing Address

37105 Brietbach Road

Property Address

37105 Brietbach Road, Park Rapids MN

City

Park Rapids

State

MN

Parcel #

270039000

Zip

56470

Complaint

Mystery letter received regarding considerable work with heavy equipment in the NE quadrant of the property with involves a considerable amount of wetlands and lake shore.

What to Inspect

work on the NE quadrant of the property

Inspection Date

10/04/16

Report of Finding

Inspections in the area went down Brietbach Rd and into driveway- did not see anything unusual. Had to go to a different site to meet contractor- so didn't have time to go up wilderness Bay rd.

Write generic letter to owners stating a complaint came into the office regarding land alteration conducted without a permit- need land alteration into the office with scope of the project for after the fact review.

Violation of Ordinance

Yes

If Yes, What Ordinance?

Chapter 8 Section 14, Chapter 8 Section 3 subsection C

Action Needed

Letter to owner regarding possible land alteration violation

Date Notified of Corrective Action

Action Deadline

Follow Up Notes

Date Sent To Co Atty

**\*\*IF SENT TO CO ATTY\*\*REFER TO LEGAL DATABASE ALSO**

