



081000000-2025



Becker County Planning & Zoning
 915 Lake Ave
 Detroit Lakes, MN 56501
 (218) 846-7314
 www.co.becker.mn.us

Certificate of Compliance Inspection Report - Permit #: SS2019-11

Owner & Property Information

Owner Name:	STEVEN & JANE CARLSON	Site Address:	20300 CO RD 131
Mailing Address:	STEVEN & JANE CARLSON 1670 NEWMAN DR IDAHO FALLS ID 83402	Township - Sec/Twp/Rng:	DETROIT - 10/139/041
Parcel #:	081000000	Legal Description:	FLOYD LAKE POINT LOT 26
Secondary Parcel #:		Designer:	Tom Falk's Backhoe Service Inc, L622 (Thomas Falk)
		Installer:	Tom Falk's Backhoe Service Inc, L622 (Thomas Falk)

Inspector Verified Specifications

Insp- Effluent Screen Installed:	No	Insp- Tank Nbr/Size:	2/1500 x2
Insp- Alarm Required:	Yes	Insp- Drainfield Type:	No Drainfield
Insp- Lift Pump in System:	No	Insp- Drainfield Size:	-
Insp- Number of Bedrooms:	2	Insp- Soil Verification:	#1- #2- #3-

Inspector Verified Setbacks


Insp- Tank Dist to Road	10+	Insp- Drainfield Dist to Road	-
Insp- Tank Dist to Nearest Prop Line	10	Insp- Drainfield Dist to Nearest Prop Line	-
Insp- Tank Dist to Nearest Structure	8 Best placement	Insp- Drainfield Dist to Nearest Structure	-
Insp- Tank Dist to Well	+50	Insp- Drainfield Dist to Well	-
Insp- Tank Dist to OHW	120+	Insp- Drainfield Dist to OHW	-
Insp- Tank Dist to Pond/Wetland	-	Insp- Drainfield Dist to Pond/Wetland	-
Insp- Tank Dist to Pressure Line	10	Insp- Drainfield Dist to Pressure Line	-

Certificate of Compliance

(Yes) Certificate is hereby granted based upon the application, addendum from, plans, specifications and all other supporting data. With proper maintenance, this system can be expected to function satisfactory, however this is not a guarantee.

Certification Date: 05/09/2019

Zoning Office Signature:



Laird Stoll - ISTS Inspector

* Certificate of Compliance is not valid unless signed by a Registered Qualified Employee *